

SA-II


4

QP Code : 11967

4

4. (a) Define the following terms :—
 (i) Carry over factor
 (ii) Distribution factor
 (b) Analyse the beam by moment distribution method and draw BMD.

16



5. Analyse the frame by stiffness method and draw BMD.

20

