
QP Code: 11967

(b) Determine shape factor for the 'T' section as shown in fig.

6



(c) Develop the flexibility matrix with respect to co-ordinate shown in fig.

8

